

Report ID: 26,578,880 1 Version: 08 Apr 2025 Created:

Make:	BMW	Model:	3201	Body Style:	Sedan		Pass	Fail	N/A
Year:	2012	Registration:		Reg Expiry:		Engine	1		1
WoF Expiry:	07 Apr 2026	Odometer:	34,000 Kms	Good No:	26578880	Oil level	~		
VIN:	WBA3B16010NP41472	Next Service:	44996	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	o purchase and t	nis can be arranged fo	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			1
D = dent R = rust	w dk			715	HILS	Operation	~		
PT = paint defe		FI		$\left(\left \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIS				74114	CV joints	~		
* = decals	- Alt			-No-		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Dodulac		Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed trea	d depth	of tyre	1 2s)
						Left front 4			mm
						Right front		3	mm
						Left rear		3	mm
Conditions During Body Inspection: Wet						Right rear		3	mm
Conditions During Body Inspection: Wet						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		L
						Operation			
Interior Comments						Electrical / Accessories			
Seats Good						Head lights	~		
	0000					Tail lights	~		
Carpets	Good					Indicators	~		<u> </u>
Panels	Cood					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		+
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		<u> </u>
General Comments						Window winder RL	~		+
Display unit screen has delaminated internally						Window winder RR	~		<u> </u>
	concentration actainmat	co memory				Rear view mirrors	~		+
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		-
						Number of keys	2		1
Pood Conditions During Test Driver						Central locking	2 1		
Road Conditions During Test Drive: Dry						Remote locking	~		+
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	-		V
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		-
	•	•					•		<u> </u>
Inspected	d by: Sione Mae					Date: 08 Apr 20	25		

I have read and understood this condition guide.

Name:

Signature: