

Basic Vehicle Condition Guide

Report ID: 26,578,977

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Coolant condition Performance

Radiator / Hoses (visual)

07 Apr 2025 Created:

Pass

~

Fail


N/A

Make: Model: Mercedes-Benz C200 **Body Style:** Wagon Year: 2012 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 28 Mar 2026 76,818 Kms 26578977

VIN: WDD2042482F807675 **Next Service:** 86900 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

07 Apr 2025 Chris Buckley Inspected by:

Name:

Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes			•	
Performance	~			
Hand Brake	>			
Tyres (lowest observed treac	depth	of tyre	es)	
Left front	7	.0	mm	
Right front	7	.0	mm	
Left rear	ear 7.0		mm	
Right rear	7	.0	mm	
Spare	Yes		5	
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation	'			
Electrical / Accessories				
Head lights	>			
Tail lights	>			
Indicators	>			
Dashboard warning lights	>			
Wipers (front & rear)	'			
Window winder FL	>			
Window winder FR	V V V V V			
Window winder RL	~			
Window winder RR	/			
Rear view mirrors	>			
Radio (basic test only)	/			
CD (basic test only)			′	
Number of keys	1			
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			1	

Reversing camera

Signature: