

## **Basic Vehicle Condition Guide**

Report ID: 26,587,422


3 Version:

08 May 2025 Created:

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2013 Registration: **GWF391** Reg Expiry: 02 Jan 2026 **Odometer:** WoF Expiry: 05 Mar 2026 188,619 Kms **Good No:** 26587422 **Next Service:** VIN: KMHSH81XSCU926575 200,000 Service History: Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Conditions During Body Inspection:** Dry

## **Under Carriage & Under Bonnet Inspection Comments**

Vehicle has belly pans. Runs on diesel fuel.

<u>Interior Comments</u>		
Seats	cracked marks	
Carpets	Average	
Panels	scratches scuffs marks	
Dashboard	scratches	

## **General Comments**

Air conditioning and heating systems good temperature and reverse camera ok.

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Timing Chain

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

12 Feb 2025 Gary Adams Inspected by: Date:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
•		•
~		
~		
depth	of tyre	es)
7	.0	mm
5	.0	mm
8.0		mm
8.0		mm
	Yes	
•		
~		
~		
~		
Air Conditioning / Heater		
~		
~		
~		
~		
~		
~		
~		
~		
<b>/</b>		
~		
~		
<b>v</b>		
~		
\( \triangle \)		
\( \times \)		
\( \times \)		
\( \times \)		·
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ

I have read and understood this condition guide.

Name: .....

Signature: .....