

Basic Vehicle Condition Guide

Report ID: 26,589,010

3 Version:

11 Apr 2025 Created:

Make: Model: Honda Vezel **Body Style:** Hatchback

Year: 2018 Registration:

Service History:

Odometer: 85,401 Kms Reg Expiry:


07 Apr 2026 VIN:

WoF Expiry:

7AT08GDHX2527414! **Next Service:** 95399 kms **Good No:** 26589010

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

FWD

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

	_
General	Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

08 Apr 2025 Eleoit Kumar Inspected by: Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	·		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	· ·	.0	mm
Right front	7.0		mm
Left rear	7	.0	mm
Right rear	7.0		mm
Spare		N/A	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	V		Ι
Electrical / Accessories			
Head lights	~		Τ
Tail lights			
Indicators	V		
Dashboard warning lights	<i>'</i>		
Wipers (front & rear)	\(\times \)		
Window winder FL	.,		
Window winder FR	v		
Window winder RL			
Window winder RR	V		
Rear view mirrors	V		
Radio (basic test only)	'		.,
CD (basic test only) Number of keys	1		
	1		1
Central locking	<i>V</i>		
Remote locking	\ <u>'</u>		-
Sat. Nav. (basic test only)	_		'
Reversing camera	'		

Signature: