

Basic Vehicle Condition Guide

Report ID: 26,591,976

Pass

1

V

/

2 Version:

27 Mar 2025 Created:

Fail

N/A

Make: Toyota Model: Aqua **Body Style:** Hatchback

Year: 2013 Registration:

Reg Expiry:

WoF Expiry: 25 Mar 2026 **Odometer:** 70,145 Kms

Good No:

26591976

VIN: 7AT0H65YX25155533

Next Service: 80,000 Kms

Service History:

Cooling System

Performance

Smoke & fumes

Engine

Oil level

Noise

Coolant condition Performance Radiator / Hoses (visual)

Transmission

Operation V Noise 1 Clutch 1 CV joints Wheel bearings

Brakes

Performance **Hand Brake**

Tyres (lowest observed tread depth of tyres) Left front 4.0 mm

Right front 4.5 mm Left rear 4.5 mm Right rear 4.5 mm

Yes

Suspension

Spare

Suspension performance Steering performance 1 Shock absorbers

Air Conditioning / Heater

Operation

Electrical / Accessories Head lights

Tail lights Indicators Dashboard warning lights / Wipers (front & rear) Window winder FL

Window winder FR Window winder RL Window winder RR Rear view mirrors Radio (basic test only)


CD (basic test only) 1 Number of keys 2 Central locking

Remote locking Sat. Nav. (basic test only) Reversing camera

> 26 Mar 2025 Date:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments		
	Seats	Good

Carpets Good **Panels** Good

Dashboard Good

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Troy Smith Inspected by:

I have read and understood this condition guide. Name:

Signature:

/

1

~

1