

Report ID: 26,592,328 1 Version: 03 Apr 2025 Created:

Make:	Toyota	Model:	Aqua	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2016	Registration:		Reg Expiry:		Engine			I	
WoF Expiry:	01 Apr 2026	Odometer:	72,445 Kms	Good No:	26592328	Oil level	~			
VIN:	7AT0H65YX25549448	Next Service:	82443	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	oort is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional of	charge.	Coolant condition	~			
						Performance	~			
Key:		=		5(0)-		Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
R = rust				20		Operation	~			
PT = paint defe	et NP				1111	Noise	~			
C = crack						Clutch			~	
P = pin dent	sc dlP				24116	CV joints	~			
* = decals		10		10		Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
						Performance	~			
Body Insp	ection Comments	Note: som	ne defects & blemishes	s may not be disp	blayed in the diagram	Hand Brake	~			
						Tyres (lowest observed tread depth of tyres)				
						Left front	5	5	mm	
						Right front	5	5	mm	
						Left rear	5	5	mm	
Conditions During Body Inspection:						Right rear	5 mm		mm	
						Spare	Yes			
Under Ca	rriage & Under Bor	net Inspectio	on Comments			Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior C						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpets	Good					Tail lights	~			
	Good					Indicators	~			
Panels	Good					Dashboard warning lights	~		<u> </u>	
Dashboa	rd Good					Wipers (front & rear)	~			
						Window winder FL	~		<u> </u>	
Concret	ommonte					Window winder FR	~			
	<u>omments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)			~	
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
Enging Tir	ning Mechanism:	Timing (Chain			Remote locking	~			
-	÷			Kma		Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspecter	Inspected by: Kilipati Mae Date: 03 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: