

Report ID: 26,592,647 3 Version: 28 Feb 2025 Created:

Make:	Mazda	Model:	CX-5	Body Style:	Wagon		Pass	Fail	N/A
Year:	2014	Registration:		Reg Expiry:		Engine	1	I	1
WoF Expiry:	25 Feb 2026	Odometer:	89,528 Kms	Good No:	26592647	Oil level	~		
VIN:	7AT0C144X25100975	Next Service:	99,526 km	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged to	r an additional o	narge.	Coolant condition	~		
						Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust				210		Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				24116	CV joints	~		
* = decals	- dle	10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significan						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	6	.0	mm
						Right front	6	.0	mm
						Left rear	5	.0	mm
Conditions During Body Inspection: Dry						Right rear	5.0 mm		
						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
FWD.						Suspension performance	~		
						Steering performance	~		
Shock al							~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	_					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking									
Remote locking							~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
							25		
Inspected by: Imraan Bryant Date: 28 Feb 2025									

I have read and understood this condition guide.

Name:

Signature: