

Report ID: 26,592,725 3 Version: 10 Mar 2025 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2016	Registration:		Reg Expiry:		Engine			L
WoF Expiry:	27 Feb 2026	Odometer:	98,777 Kms	Good No:	26592725	Oil level	~		
VIN:	7AT0C13JX25306184	Next Service:	108,000 kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	oort is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional of	charge.	Coolant condition	~		
						Performance	~		
Key:				5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust				20		Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack				TTM.		Clutch			~
P = pin dent	HP				2414	CV joints	~		
* = decals	- dle	10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
i i significant		\mathbf{O}				Performance	~		
Body Insp	ection Comments	Note: som	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			es)
						Left front	8.	.0	mm
						Right front	8.	.0	mm
						Left rear	8.	.0	mm
Conditions During Body Inspection: Dry						Right rear	8.0 mm		
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			-
Fwd						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior C						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		<u> </u>
Dashboa	rd Card					Wipers (front & rear)	~		
	rd Good					Window winder FL	~		
Concerto	ammasta					Window winder FR	~		
	<u>comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
L						Number of keys	1		1
Road Conditions During Test Drive: Dry						Central locking	~		
Enging Tir	ning Mechanism:	Timing (Chain			Remote locking	~		<u> </u>
-	•			Kma		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Marlon Espena Date: 28 Feb 2025									

I have read and understood this condition guide.

Name:

Signature: