

Report ID: 26,597,931 11 Version: 20 Feb 2025 Created:

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2017	Registration:	QRP504	Reg Expiry:	08 Sep 2025	Engine	I		L
WoF Expiry:		Odometer:	80,985 Kms	Good No:	26597931	Oil level	~		
VIN:	7AT0GK0CX22102469	Next Service:	91000kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		6	Danta harra nat	la a constituição de la constituição	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
		_				Performance	V		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	sc 6/6			The	EID S	Operation	~		
R = rust PT = paint def				\prod	JHH	Noise	~		
C = crack						Clutch	~		
P = pin dent						CV joints	~		
* = decals	sc 916			The	ETTPS-	Wheel bearings	~		
SC = stone chips						Brakes			L
W = significant scuffs						Performance	~		
		Note: son	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments				a) ca in the alagram	Tyres (lowest observed tread	-	of tyre	 ()
						Right front	3.		 mm
						Left rear	4.		mm
Conditions During Rody Inspection						Right rear			 mm
Conditions During Body Inspection: Dry						Spare	No		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
	Air Conditioning / Heater	•		l					
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Cood					Dashboard warning lights	~		
	Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		Ľ –
							2 V		
Road Conditions During Test Drive: Dry Remote locking							~		
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
	-								
Inspected by: Lindsay Malpas Date: 13 Feb 2025									

I have read and understood this condition guide.

Name:

Signature: