

Basic Vehicle Condition Guide

Report ID: 26,606,256


Version:

26 Feb 2025 Created:

Make: Model: Volkswagen Golf **Body Style:** Hatchback Year: 2011 Registration: JYJ74 Reg Expiry: 17 Mar 2025 WoF Expiry: **Odometer:** 26 Aug 2025 155,348 Kms **Good No:** 26606256 VIN: WVWZZZ1KZBW212910 Next Service: 165000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tested battery and passed runs on 95/98 octane fuel

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Average		

General Comments

Air conditioning and heating system okay at inspection time

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

20 Feb 2025 **Gary Adams** Inspected by: Date:

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
•		
~		
~		
d depth	of tyre	es)
4.0		mm
5.0		mm
4.0		mm
3.0		mm
Yes		
~		
~		
~		
		1
~		
		1
~		
~		
~		
~		
~		
~		
1		
V		
V		
_	1	
~		
v v		
~		
\(\tau \)		
\(\times \)		
\(\times \)		
\(\times \)		
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

I have read and understood this condition guide.

Name:

Signature: