

Report ID: 26,608,870 3 Version: 01 May 2025 Created:

Signature:

Make:	Honda	Model:	Shuttle	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2015	Registration:		Reg Expiry:		Engine	ıl		L
WoF Expiry:	25 Mar 2026	Odometer:	70,352 Kms	Good No:	26608870	Oil level	~		
VIN:	7AT08G2YX25010548	Next Service:	80,350 km	Service Histor	r y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		$-\infty$				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust				715		Operation	~		
PT = paint defe	ect NP	FI		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIG				2414	CV joints	~		
* = decals	MA					Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significant						Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	depth	of tyre	25)
						Left front 7.0 mr			mm
						Right front	7.	0	mm
						Left rear	7.	0	mm
Conditions During Body Inspection: Dry						Right rear	7.0 mm		mm
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
FWD.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			L
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	ord Good					Window winder FL	~		
	•					Window winder FR	~		
General Comments						Window winder RL	~		
Stereo code 09897						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking							~		
Remote locking							~		
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: Imraan Bryant Date: 27 Mar 2025									

I have read and understood this condition guide.

Name: