

				•		
Interior Comments		_	Electrical / Accessories			
Seats	Good		Head lights	~		
Carnota		- 1	Tail lights	~		
Carpets	Good		Indicators	~		
Panels	Good		Dashboard warning lights	~		
	Good		Wipers (front & rear)	~		
Dashboard			Window winder FL	~		
			Window winder FR	~		
<u>General Comments</u>			Window winder RL	~		
Right front door lock activator is not operating.			Window winder RR	~		
			Rear view mirrors	~		
			Radio (basic test only)	~		
			CD (basic test only)	~		
			Number of keys	2		
Road Conditions During Test Drive: Dry			Central locking		~	
			Remote locking		~	
Engine Timing Mechanism: Timing Chain		Sat. Nav. (basic test only)			~	
Evidence of Cam	Belt Replacement: Not Applicable Kms:		Reversing camera			~
Inspected by: Yuki Itohara			Date: 20 Feb 2025			

I have read and understood this condition guide.

Name: .....

Signature: .....

V