

Report ID: 26,612,089 3 Version: 06 Mar 2025 Created:

Make:	Honda	Model:	Accord	Body Style:	Sedan		Pass	Fail	N/A
Year:	2014	Registration:	PLR957	Reg Expiry:	30 Apr 2025	Engine	1	<u> </u>	1
WoF Expiry:		Odometer:	112,832 Kms	Good No:	26612089	Oil level	~		
VIN:	7AT08G13X22013244	Next Service:	121000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	IS 6/6			The	SC W	Operation	~		
R = rust PT = paint def				í In		Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals	s pik			AL.	ENR	Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs						Performance 🖌			T
		Note: son	e defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	ofture	
LHR second layer showing, Stone chips in front screen. No spare wheel provided by vehicle manufacturer but						Tyres (lowest observed tread depth of tyres)			
emergency tire inflation device is in the boot.						Left front		5.0 mm	
						Right front		.0	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear	7.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare N/A			
onder carriage & onder bonnet inspection comments						Suspension			1
Tested batt	ery and passed. Vehicle	has belly pan. R	uns on 91 octane fuel.			Suspension performance	~		
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater	1		Т
Interior Comments						Operation	~		
						Electrical / Accessories			1
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	0000					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Card					Wipers (front & rear)	~		
Dastibua	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Air conditioning and heating system good temperature along with reverse camera okay at inspection time.						Window winder RR	~		
Passengers	mirror does not retract.					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	Central locking	~						
			Dry			Remote locking	~		1
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
						L			
Inspected by: Gary Adams Date: 24 Feb 2025									
I have read and understood this condition guide. Name:									