

Report ID: 26,619,319 1 Version: 26 Feb 2025 Created:

Make:	Mazda	Model:	Bt-50	Body Style:	Utility		Pass	Fail	N/A
Year:	2019	Registration:	LZH657	Reg Expiry:	06 Feb 2026	Engine			
WoF Expiry:	22 Mar 2025	Odometer:	233,818 Kms	Good No:	26619319	Oil level	~		
VIN:	MM0UR0YG100936497	Next Service:	29/1/25 or 240900km	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage.	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a run mechan	ical inspection prior to	purchase and tr	lis can be arranged to	or an additional C	narge.	Coolant condition	~		
	SC		S P SC S P SC		S SC	Performance	~		
Key: S = scratch		=(0)		5(0)-		Radiator / Hoses (visual)	~		
						Transmission			
R = rust	sc w			10		Operation	~		
PT = paint defe	ect NP	1				Noise	~		
C = crack					РТ	Clutch			~
P = pin dent	HE				24145	CV joints	~		
* = decals SC = stone chips						Wheel bearings	۲		
W = significant scuffs						Brakes			
	SC		S			Performance	<		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
					Tyres (lowest observed tread depth of tyres)				
Stone chips in windscreen.						Left front	6 mm		mm
						Right front	e	5	mm
						Left rear	5	5	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		mm
						Spare	Yes		
Surface corrosion under vehicle.						Suspension			
						Suspension performance	~		
						Steering performance	~		
	Shock absorbers	~							
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
Concert						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Vehicle dro	ve well.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		
Road Conditions During Test Drive: Dry Central loc							~		
Remote locking							~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Aaron Johnson Date: 26 Feb 2025									

I have read and understood this condition guide.

Name:

Signature: