

Basic Vehicle Condition Guide

Report ID: 26,621,251


2 Version:

11 Apr 2025 Created:

Make: Model: Mitsubishi Mirage **Body Style:** Hatchback Year: 2014 Registration: HNA3 Reg Expiry: 01 Jul 2025 **Odometer:** WoF Expiry: 21 Jan 2026 45,572 Kms **Good No:** 26621251 VIN: MMAXTA03AEH016315 **Next Service:** 60,000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Rear bumper mouldings coming off

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Andre Richardson 08 Apr 2025 Inspected by:

| Pass | Fail | N/A |
|----------|---------------------------------------|-----|
| | | |
| ~ | | |
| ~ | | |
| ~ | | |
| ~ | | |
| | | |
| ~ | | |
| ~ | | |
| ~ | | |
| | 1 | |
| ~ | | |
| ~ | | |
| | | ~ |
| ~ | | |
| ~ | | |
| | | |
| ~ | | |
| ~ | | |
| depth | of tyre | es) |
| 4 | .0 | mm |
| 4 | .0 | mm |
| 5.0 | | mm |
| 5 | .0 | mm |
| | Yes | |
| | ı | ı |
| ~ | | |
| ~ | | |
| ~ | | |
| | I | I |
| ~ | | |
| | I | |
| ~ | | |
| ~ | | |
| <i>'</i> | | |
| • | | |
| • | | |
| • | | |
| • | | |
| • | | |
| • | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| <i>'</i> | | |
| | | |
| | | |
| | マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ | |

I have read and understood this condition guide.

Name:

Signature: