

Report ID: 26,628,874 2 Version: 10 Apr 2025 Created:

Make:	Peugeot	Model:	3008	Body Style:	SUV		Pass	Fail	N/A
Year:	2017	<b>Registration:</b>	LZP853	Reg Expiry:	07 Apr 2025	Engine			
WoF Expiry:	17 Sep 2025	Odometer:	66,467 Kms	Good No:	26628874	Oil level	~		
VIN:	VF3MCBHZWHS211979	Next Service:	76141	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
	S S		S P S	S	S	Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	s AR			210		Operation	~		
PT = paint defe	ect NP				10111	Noise	~		
C = crack				TTY .		Clutch			~
P = pin dent	s sc				2416	CV joints	~		
* = decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scurs S S S S S S S S						Performance	~		
   Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
<u>/</u>						Tyres (lowest observed tread depth of tyres)			
					Left front	5 mm		mm	
						Right front	5 mm		mm
						Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear	7 mm		
			-			Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	ition 🖌		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	<u> </u>					Tail lights		~	
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd c i					Wipers (front & rear)	~		
	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1	1	
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism. That a Chata						Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Bryce Steele Date: 10 Apr 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....