

Report ID: 26,631,046 3 Version: 01 May 2025 Created:

Make:	Holden	Model:	Captiva 7	Body Style:	SUV		Pass	Fail	N/A
Year:	2014		HGP166	Reg Expiry:	17 Jul 2025	Engine			
	26 Feb 2026	Odometer:	157,566 Kms	Good No:	26631046	Oil level	~		
VIN:	KL3CD265JDB078875			Service Histor		Smoke & fumes	~		
	12328203388070073		107331			Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
						Coolant condition Performance	~		
Key:	S	-0	SP SP		S P		~		
S = scratch	R	- (U)	<u>C</u>	10/2	~	Radiator / Hoses (visual)	~		
D = dent	SPT AL			100	HID S	Transmission			
R = rust				$1 \land$	SHIK	Operation	~		
PT = paint defe	ect M			$\square \cup$	S S	Noise	~		
C = crack P = pin dent	Itt					Clutch			~
* = decals	SRSC DI				EL SPSC	CV joints	~		
SC = stone chips						Wheel bearings	✓		
W = significant scuffs						Brakes			
	S R SC		S S P		S	Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	blayed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	6.5 mm		mm
						Right front	6.5 mm		mm
						Left rear	3.0)	mm
Conditions During Body Inspection: Dry						Right rear	3.0 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Aftermarket suspension						Suspension performance	~		
, arcennance	suspension					Steering performance	~		-
						Shock absorbers	~		
						Air Conditioning / Heater	11	1	
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Avelage					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys			~
	1		_				2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
				11113.		Reversing camera	~		
Inspected by: Darren Beban Date: 11 Mar 2025									

I have read and understood this condition guide.

Name:

Signature: