

Report ID: 26,631,836 5 Version: 10 Apr 2025 Created:

Make:	Volkswagen	Model:	Golf	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2014	Registration:		Reg Expiry:		Engine			
WoF Expiry:	17 Mar 2026	Odometer:	13,968 Kms	Good No:	26631836	Oil level	~		
VIN:	WVWZZZAUZEW251884	Next Service:	23,900 km	Service Histor	y: No	Smoke & fumes	~		
	_					Performance	~		
	port is not a warranty a quide only. Consid		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	lical inspection prior to	o purchase and th	his can be arranged fo	or an additional of	charge.	Coolant condition	~		
						Performance	~		
Key:		$-\infty$		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission	II		1
D = dent R = rust				710		Operation	~		
PT = paint def	ect NP			$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIG				7414	CV joints	~		
* = decals				- John		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Podulaci	action Commont	Note: som	ne defects & blemishe	s may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
						Left front 7.0 mm			
						Right front	7.	0	mm
						Left rear	7.	0	mm
Conditions During Body Inspection:						Right rear	7.	0	mm
	is barning body inc	Spare Yes							
Under Carriage & Under Bonnet Inspection Comments						Suspension			
FWD.						Suspension performance	~		
FWD.						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			I
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera	~		
									1
Inspected by: Eleoit Kumar Date: 09 Apr 2025									

I have read and understood this condition guide.

Name:

Signature: