

Report ID: 26,635,644 1 Version: 12 May 2025 Created:

Make:		Model:	C10	Rody Ctulos	Van		Pace	Eatl	N/A
Make: Year:	LDV 2017		G10	Body Style: Bog Expiry:	Van	Engine	Pass	Fail	
WoF Expiry:		Registration: Odometer:	KLU397 135,149 Kms	Reg Expiry: Good No:	22 Mar 2025 26635644	Engine Oil level	~		<u> </u>
VIN:	28 Apr 2026 LSKG4BL10HA042350			Service Histor		Smoke & fumes	<i>v</i> <i>v</i>		+
	LSKG4DL10HA042550	NEXT SEIVICE.	140000	Service mistor	y. res	Performance			+
	port is not a warranty					Noise	~		
This report is	a guide only. Considesting undertaken. The	eration is made vehicle has beer	for age and mileage	. Parts have not	been dismantled or Vendor recommends		~		
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional of	charge.	Cooling System			1
						Coolant condition	~		
Key:			*			Performance	~		
S = scratch						Radiator / Hoses (visual)			
D = dent	sc			100	HID S*W	Transmission			1
R = rust				10		Operation	~		
PT = paint def	ect N			$\square \cup$		Noise	~		
C = crack P = pin dent	Hr					Clutch	~		
* = decals	* dl					CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			.
						Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	5	.0	mm
						Right front	5	.0	mm
						Left rear	1	.5	mm
Conditions During Body Inspection:						Right rear	1.5 mm		
						Spare Yes			
Under Ca	irriage & Under Bor	nnet Inspectio	on Comments			Suspension			
Rear tyres lo	ow but OK at WOF					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	.					Wipers (front & rear)	~		
Dashboa	ord Good					Window winder FL	~		
						Window winder FR	~		1
<u>General Comments</u>						Window winder RL			~
Surface rust around body WOF ok						Window winder RR			~
	-					Rear view mirrors	~		1
						Radio (basic test only)	~		1
						CD (basic test only)			~
						Number of keys	1		J
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		1
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		+
L						-			
Inspecte	d by: John Jones					Date: 05 Mar 20	25		

I have read and understood this condition guide.

Name:

Signature: