

Report ID: 26,635,848 1 Version: 13 Mar 2025 Created:

Year: 2012 Registr WoF Expiry: 24 Mar 2026 Odome VIN: 7AT0C139X24100143 Next Set Note: This report is not a warranty This report is a guide only. Consideration is diagnostic torting undottaken. The vehicle here	ter: 113,985 Kms	Body Style: Reg Expiry: Good No:	Wagon 26 Aug 2025 26635848	Engine Oil level			L
WoF Expiry: 24 Mar 2026 Odome VIN: 7AT0C139X24100143 Next Set Note: This report is not a warranty This report is a guide only. Consideration is	ter: 113,985 Kms		26635848	Oilloval	1 1		
Note: This report is not a warranty This report is a guide only. Consideration is	rvice: 123,000		20033010	Onlevel	~		
This report is a guide only. Consideration is		Service Histor	y: No	Smoke & fumes	~		
This report is a guide only. Consideration is				Performance	~		
	made for any and miles	an Darte have not	been dismonthed or	Noise	~		
ulagnostic testing undertaken. The vehicle h	as been driven up to 50kn	n/h from cold. The	/endor recommends	Cooling System	-		I
a full mechanical inspection prior to purchas	e and this can be arranged	l for an additional c	harge.	Coolant condition	~		
" S	<u> </u>		S	Performance	~		
Key:	<u>n</u>	50-		Radiator / Hoses (visual)	~		
S = scratch	YAT		<u>کھر</u>	Transmission			·
D = dent R = rust		215	HIL S	Operation	~		
PT = paint defect		$\left[\left(\right) \right]$		Noise	~		
C = crack		$+ \mathbf{\nabla}$	S	Clutch			~
P = pin dent		$ \rightarrow $	74114	CV joints	~		
* = decals S 919			ALC S	Wheel bearings	~		
SC = stone chips		POL	* —	Brakes			L
W = significant scuffs S	S S		S	Performance	~		
Redular comments	ote: some defects & blemis	hes may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments			Tyres (lowest observed tread depth of tyres)			es)	
				Left front	7.	0	mm
			Right front	6.	5	mm	
				Left rear	6.	5	mm
Conditions During Body Inspection: Dry			Right rear	6.5 mm			
Contactions Daring Dody inspection. Dry			Spare	N/A			
Under Carriage & Under Bonnet Ins	pection Comments			Suspension			
Aftermarket Suspension & Intake Pipe				Suspension performance	~		
				Steering performance	~		
				Shock absorbers	~		
				Air Conditioning / Heater	1 1		1
				Operation	~		
Interior Comments			Electrical / Accessories				
Seats Good				Head lights	~		
				Tail lights	~		
Carpets Good				Indicators	~		
Panels Good				Dashboard warning lights	~		
				Wipers (front & rear)	~		
Dashboard Good				Window winder FL	~		
				Window winder FR	~		
General Comments				Window winder RL	~		
Fog Lights Disconnected				Window winder RR	~		
				Rear view mirrors	~		
				Radio (basic test only)	~		
				CD (basic test only)	~		
				Number of keys	2		
Road Conditions During Test Drive: Dry Central locking				~			
				Remote locking	~		
	ning Chain			Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement:	Not Applicable	Kms:		Reversing camera	~		
					25		
Inspected by: Samuel Weir				Date: 13 Mar 20	25		

I have read and understood this condition guide.

Name:

Signature: