

Report ID: 26,636,604 3 Version: 08 Mar 2025 Created:

Make:	lsuzu	Model:	D-MAX	Body Style:	Utility		Pass	Fail	N/A
Year:	2018	Registration:	LEL586	Reg Expiry:	30 Jul 2025	Engine	1		
WoF Expiry:	18 Mar 2026	Odometer:	69,618 Kms	Good No:	26636604	Oil level	~		
VIN:	MPATFR85JHT002792	Next Service:	78000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and tr	lis can be arranged to	r an additional C	.narge.	Coolant condition	~		
			S			Performance	~		
Key: S = scratch		=		5(0)-		Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust				10		Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack				TTY .		Clutch			~
P = pin dent	sc de				241 <u>16</u>	CV joints	~		
* = decals		10		10	SW SW	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
					W	Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
<u> </u>						Tyres (lowest observed tread depth of tyres)			
						Left front	8.	.0	mm
						Right front	8.0		mm
						Left rear	8.	.0	mm
Conditions During Body Inspection: Dry						Right rear	8.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
	Shock absorbers	~							
						Air Conditioning / Heater	.er		
Interior Comments						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	and Assessed					Wipers (front & rear)	~		
Dastibua	rd Average					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking							~		
	mina Masharian	T' '				Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Greg Morgan Date: 04 Mar 2025									

I have read and understood this condition guide.

Name:

Signature: