

Report ID: 26,636,636 5 Version: 25 May 2025 Created:

Make:	Hyundai	Model:	Santa FE	Body Style:	SUV		Pass	Fail	N/A
Year:	2013	<b>Registration:</b>	GTF304	Reg Expiry:	10 Sep 2025	Engine	1		
WoF Expiry:	04 Feb 2026	Odometer:	115,128 Kms	Good No:	26636636	Oil level	~		
VIN:	KMHSH81XSCU920040	Next Service:	124000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
	S S		S S	S	S	Performance	~		
Key:	is lis	-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust	S SC W			210	HIVS	Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	ssc dP				24114	CV joints	~		
* = decals		1		10	ELC S	Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	S S		SP SP	S	S	Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	5.	0	mm
						Right front	5.	0	mm
						Left rear	6.	0	mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Daabbaa						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	_					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry							~		
Engine T:	ning Machanian	T:	<sup>c</sup> hain			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: My Auto Shop Date: 07 Mar 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....