

7AT0C13JX25109705

## **Basic Vehicle Condition Guide**

Report ID: 26,638,711

3 Version:

27 May 2025

Make: Model: Mazda Axela **Body Style:** Hatchback

Year: 2014

VIN:

Service History:

Registration:

Next Service:

Reg Expiry:


WoF Expiry: 07 May 2026

**Odometer:** 46,260 Kms **Good No:** 26638711

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

56,256 Kms



## **Body Inspection Comments**

Tyre repair kit instead of spare wheel. Both side mirrors scuffed.

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

## **General Comments**

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Timing Chain

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

Created: 27 May 2025				
	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance	<i>v v</i>			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission				
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	•			
Tyres (lowest observed tread	depth	of tyre	2S)	
Left front	6	.5	mm	
Right front	6.5		mm	
Left rear		.5	mm	
Right rear	6.5		mm	
Spare		N/A		
Suspension	1	ı	1	
Suspension performance	~			
Steering performance	<i>V</i>			
Shock absorbers	~			
Air Conditioning / Heater	· .	T	1	
Operation	~			
Electrical / Accessories				
Head lights	·			
Tail lights	•			
Indicators	\( \triangle \)			
Dashboard warning lights				
Wipers (front & rear) Window winder FL	<b>V</b>			
	<b>V</b>			
Window winder FR Window winder RL	~			
	~			
Window winder RR  Rear view mirrors				
	<i>'</i>			
Radio (basic test only)	<i>-</i>			
CD (basic test only)	2			
Number of keys	2			

11 May 2025 Troy Smith Inspected by: Date:

~

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)