

Report ID: 26,644,555 2 Version: 11 Mar 2025 Created:

Make:	Suzuki	Model:	SX4 S-Cross	Body Style:	SUV		Pass	Fail	N/A
Year:	2018	Registration:	LJD886	Reg Expiry:	11 Sep 2025	Engine			
WoF Expiry:		Odometer:	97,225 Kms	Good No:	26644555	Oil level	~		
VIN:	TSMJYAA2S00555660	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty			-		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance	~		
Key:	SC	-0			S W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent				1 - L	EID S				1
R = rust				10		Operation	~		
PT = paint defe	ect			$\square \cup$	SC	Noise	~		
C = crack P = pin dent	Ho			-		Clutch			~
* = decals	sc db					CV joints	~		
SC = stone chi	ps US			1a		Wheel bearings	~		
W = significant scuffs						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	5.	.0	mm
						Right front	5.	.0	mm
						Left rear	5.	.0	mm
Conditions During Body Inspection: Dry						Right rear	5.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			L
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		<u> </u>
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		+
Dashboa	ird 1 remote o	lamaged				Window winder FL	~		
	I					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	2		~
						Number of keys	2		<u> </u>
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Tir	ming Mechanism:	Timina	Chain			Remote locking	~		
						Sat. Nav. (basic test only)	~		
			lot Applicable	11113.		Reversing camera	~		
Inspected	d by: Greg Morgan					Date: 06 Mar 20	25		

I have read and understood this condition guide.

Name:

Signature: