

Basic Vehicle Condition Guide

Report ID: 26,651,107


Version: 2

Created: 09 Apr 2025

Make: Model: Suzuki Swift **Body Style:** Hatchback Year: 2023 Registration: QGS436 Reg Expiry: 13 Apr 2025 **Odometer:** WoF Expiry: 14 Nov 2026 43,228 Kms **Good No:** 26651107 VIN: JSAAZCA3S00584533 **Next Service:** 46921 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

No underbody inspection

| <u>Interior Comments</u> | | | |
|--------------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Inspected by:

Hybrid

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Melissa Wilson Date: 09 Apr 2025

| | Pass | Fail | N/A |
|------------------------------|--------------|---------|----------|
| Engine | 1 433 | 1 an | IN/A |
| Oil level | V | | |
| Smoke & fumes | <i>y</i> | | |
| Performance | \(\times \) | | |
| Noise | • | | |
| Cooling System | | | |
| Coolant condition | | | |
| Performance | | | |
| | , | | |
| Radiator / Hoses (visual) | • | | |
| Transmission | | | |
| Operation | • | | |
| Noise | <i>'</i> | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ' | | |
| Brakes | 1 | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 3 | .5 | mm |
| Right front | 3 | .5 | mm |
| Left rear | 3 | | mm |
| Right rear | 3 | 3 | mm |
| Spare | | N/A | |
| Suspension | | | |
| Suspension performance | ~ | | |
| Steering performance | <i>V</i> | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | ı | | ı |
| Operation | ~ | | |
| Electrical / Accessories | l | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | · | | |
| Wipers (front & rear) | | | |
| Window winder FL | V | | |
| Window winder FR | ~ | | |
| Window winder RL | ~ | | |
| Window winder RR | | | |
| Rear view mirrors | V | | |
| | V | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | | | ' |
| Number of keys | 1 | | |
| Central locking | ' | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | | | ~ |
| Reversing camera | ~ | | |
| Date: 09 Apr 202 |) [| | |

I have read and understood this condition guide.

Name:

Signature: