

Report ID: 26,651,963 2 Version: 11 May 2025 Created:

Make:	Honda	Model:	CRV	Body Style:	SUV		Pass	Fail	N/A
Year:	2012	Registration:		Reg Expiry:	30 Apr 2025	Engine			L
WoF Expiry:		Odometer:	233,733 Kms	Good No:	26651963	Oil level	~		
VIN:	JHLRM4890CC203378			Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I I		1 12 11 1	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent	HIC				세비	CV joints	~		
* = decals SSC 919 SSC						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC						Performance	~		
		Note: son	ne defects & blemishes	mav not be disc	laved in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	-	of tyre	es)
						Left front 2.0 mr			
						Right front	2.		 mm
						Left rear	5.		mm
Conditions During Pody Inspections Day						Right rear	5.		 mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Vehicle has	s belly pans. Runs on 91	octane fuel				Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats Average						Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	ľ					Window winder FR	~		
General Comments						Window winder RL	~		
Light trans shudder in 2nd.40kms Air conditioning and heating system good temperature along with reverse						Window winder RR	~		
camera. Passenger mirror doesn't retract						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking									
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Na									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Gary Adams Date: 13 Mar 2025									

I have read and understood this condition guide.

Name:

Signature: