

Report ID: 26,652,471 1 Version: 26 Mar 2025 Created:

Make:	Subaru	Model:	Impreza	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2010	<b>Registration:</b>	MMD724	Reg Expiry:	20 Mar 2025	Engine	1	I	1
WoF Expiry:	11 Oct 2025	Odometer:	198,730 Kms	Good No:	26652471	Oil level	~		
VIN:	7AT0GF09X18009645	Next Service:	208718	Service Histor	<b>y:</b> Yes	Smoke & fumes	r		
						Performance	~		
	port is not a warranty		for any and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
a full mechan	ical inspection prior to	purchase and t	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
			DD			Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	SC DE			715		Operation	~		
PT = paint def		FI		$\left[ \left( \right) \right]$		Noise	~		
C = crack				$+ \mathbf{\nabla}$	R SC	Clutch	~		
P = pin dent	HE				74114	CV joints	~		
* = decals	PSC 916			-Jul-		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Dedulae		Note: son	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
Front bumper poor fit.									mm
						Right front		.0	mm
						Left rear		.0	mm
Conditio	as During Body Ins	nection:				Right rear		.0	mm
Conditions During Body Inspection: Dry						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	V		
						Tail lights	V		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	· ·					Window winder FR	~		
General Comments						Window winder RL	~		
Sub woofer in boot. A/C working at time of inspection.						Window winder RR	~		
	-					Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 140,000						Reversing camera			~
	LL Devilence LL						25		
Inspecte	d by: Reuben Harvey					Date: 12 Mar 20	25		

I have read and understood this condition guide.

Name: .....

Signature: .....