

Basic Vehicle Condition Guide

Report ID: 26,654,671


Version:

18 Mar 2025 Created:

Make: Model: Ford Territory **Body Style:** SUV Year: 2014 Registration: HHB562 Reg Expiry: 27 Mar 2025 WoF Expiry: **Odometer: Good No:** 24 Mar 2026 192,623 Kms 26654671 VIN: 6FPAAAJGATDE53073 Next Service: 202618 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

All wheel drive

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	VVV		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	<i>V V</i>		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed treac	depth	of tyre	:s)
Left front	4	.0	mm
Right front	6.5		mm
Left rear	5.0		mm
Right rear	4.5		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	1		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	V V V V V V		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

Signature:

18 Mar 2025 Jaykib Collins Inspected by:

Name: