

Basic Vehicle Condition Guide

Report ID: 26,659,393


Version:

Created: 14 Mar 2025

Make: Model: Honda Jazz **Body Style:** Hatchback Year: 2014 Registration: HKK219 Reg Expiry: 02 Oct 2025 WoF Expiry: **Odometer:** 28 Mar 2026 86,624 Kms **Good No:** 26659393 VIN: 7A3GK5M004X304926 **Next Service:** 98,000 Kms Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Hoani Saunders Date: 13 Mar 2025

| | Pass | Fail | N/A | | |
|------------------------------|---------------------------------------|---------|----------|--|--|
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | V V V | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | ン ソ ソ | | | | |
| Radiator / Hoses (visual) | > | | | | |
| Transmission | | | | | |
| Operation | > | | | | |
| Noise | / | | | | |
| Clutch | ~ | | | | |
| CV joints | > > > > > > > > > > > > > > > > > > > | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | l depth | of tyre | es) | | |
| Left front | 3 | .7 | mm | | |
| Right front | 4.1 | | mm | | |
| Left rear | 8 | | mm | | |
| Right rear | 8 | | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| Suspension performance | ' | | | | |
| Steering performance | ~ | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | ~ | | | | |
| Wipers (front & rear) | V V V V V V | | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | | | ' | | |
| Number of keys | 2 | | | | |
| Central locking | • | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ' | | |
| Reversing camera | | | <u> </u> | | |
| | | | | | |

I have read and understood this condition guide.

Name:

Signature: