

Report ID: 26,670,234 2 Version: 08 May 2025 Created:

Make:	Toyota	Model:	Corolla	Body Style:	Wagon		Pass	Fail	N/A
Year:	2016	Registration:	RCP838	Reg Expiry:	25 Sep 2025	Engine			
WoF Expiry:	30 Apr 2026	Odometer:	100,162 Kms	Good No:	26670234	Oil level	~		
VIN:	7AT0H607X24139294	Next Service:	110,130	Service Histor	y: No	Smoke & fumes	~	L	
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust				215	HIV	Operation	~		
PT = paint defe				$\left[\left(\right) \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				7414	CV joints	~		
* = decals	- Alt			The second		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	w					Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
No spare. Runflat kit						Left front	3.0 mm		mm
						Right front	3.	.0	mm
						Left rear	3.	.0	mm
Conditions During Body Inspection: Dry						Right rear	3.0 mm		mm
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbe						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Coord					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd c i					Wipers (front & rear)	~		
	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
CD (ba									~
Number of keys							2		
Road Conditions During Test Drive: Dry Central locking							~		
Engine Timing Mechanism:							~		
Engine Timing Mechanism: Unknown Evidence of Cam Balt Banla compant: Next A sultable and Kmst									~
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera								•	
Inspected by: Tyler Le Bherz Date: 17 Mar 2025									

I have read and understood this condition guide.

Name:

Signature: