

Report ID: 26,670,571 2 Version: 16 May 2025 Created:

Make:	Holden	Model:	Cruze	Body Style:	Sedan		Pass	Fail	N/A
Year:	2014		HKL252	Reg Expiry:	30 Apr 2025	Engine			L
WoF Expiry:		Odometer:	73,967 Kms	Good No:	26670571	Oil level	~		
VIN:	6G1PE5EN9EL938226	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I II		1 B AL	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	PT	-0	LP		W	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	w Gle			1n-		Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack				$+$ $\vee$		Clutch	-		~
P = pin dent	Ho					CV joints	~		•
* = decals	PSC PK			AL.	EII PR-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs W S P S P W S D						Performance	~		
		Note: son	he defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Inst	pection Comments	1016.301	le delects & blemisties	indy not be disp	layed in the diagram			ofture	
						Tyres (lowest observed tread depth of tyres)			
						Left front	5		mm
						Right front	5		mm
L						Left rear	6	-	mm
Conditions During Body Inspection: Dry									mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
		meenspeede	<u>in comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
Concret	ommonto					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: No Kms:						Reversing camera	~		
Increast-	Inspected by: Yuki Itohara Date: 19 Mar 2025								
Inspected by: Tuki tonara Date: 19 Mai 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....