

Report ID: 26,673,073 1 Version: 09 Apr 2025 Created:

| Make:  | Mitsubishi                                     | Model:               | ASX                    | Body Style:       | SUV  |  | Pass                           | Fail | N/A |
|--|--|----------------------|------------------------|-------------------|--|--|--------------------------------|------|-----|
| Year:  | 2021   | <b>Registration:</b> | NQC381                 | Reg Expiry:       | 30 Oct 2025                                  | Engine                                 |                                |      |     |
| WoF Expiry:  |  | Odometer:            | 120,470 Kms            | Good No:          | 26673073                                     | Oil level                              | ~                              |      |     |
| VIN:   | JMFXTGA2WMU013564                              | Next Service:        | 135000                 | Service Histor    | 🗸 Yes  | Smoke & fumes                          | ~                              |      |     |
| _  |  |                      |                        |                   |  | Performance                            | ~                              |      |     |
|  | port is not a warranty<br>a quide only Conside | eration is made      | for age and mileage    | Parts have not    | been dismantled or                           | Noise                                  | ~                              |      |     |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. |  |                      |                        |                   |  | Cooling System                         |                                |      |     |
| a full mechan  | ical inspection prior to                       | purchase and tr      | his can be arranged to | r an additional c | narge.                                       | Coolant condition                      | ~                              |      |     |
|  | l w  |                      | S SC S SC              | S                 | SC   | Performance                            | ~                              |      |     |
| Key:   |  | =                    |                        | 500               |  | Radiator / Hoses (visual)              | ~                              |      |     |
| S = scratch<br>D = dent  |  |                      |                        |                   |  | Transmission                           |                                |      |     |
| D = dent<br>R = rust SC SC SC  |  |                      |                        |                   |  | Operation                              | ~                              |      |     |
| PT = paint defe  | ect NP   | 1                    |                        |                   |  | Noise                                  | ~                              |      |     |
| C = crack  |  |                      |                        |                   | SC   | Clutch                                 |                                |      | ~   |
| P = pin dent   | HE   |                      |                        |                   | 2416   | CV joints                              | ~                              |      |     |
| * = decals<br>SC = stone chips   |  |                      |                        |                   |  | Wheel bearings                         | ~                              |      |     |
| W = significant scuffs   |  |                      |                        |                   |  | Brakes                                 |                                |      |     |
|  | W  | $\sim$               | S SC S P SC            | W                 |  | Performance                            | ~                              |      |     |
| Body Insp  | pection Comments                               | Note: som            | e defects & blemishes  | may not be disp   | layed in the diagram                         | Hand Brake                             | ~                              |      |     |
|  |  |                      |                        |                   | Tyres (lowest observed tread depth of tyres) |  |                                |      |     |
|  |  |                      |                        |                   | Left front                                   | 5 r                                    |                                | mm   |     |
|  |  |                      |                        |                   |  | Right front                            | 3.5 n                          |      | mm  |
|  |  |                      |                        |                   |  | Left rear                              | 3                              | 8    | mm  |
| Conditions During Body Inspection: Wet   |  |                      |                        |                   |  | Right rear                             | 3.5 mm                         |      | mm  |
|  |  |                      |                        |                   |  | Spare                                  | Yes                            |      |     |
| No underbody inspection  |  |                      |                        |                   |  | Suspension                             |                                |      |     |
|  |  |                      |                        |                   |  | Suspension performance                 | ~                              |      |     |
|  |  |                      |                        |                   |  | Steering performance                   | ~                              |      |     |
| Shock absorbers  |  |                      |                        |                   |  |  | ~                              |      |     |
|  |  |                      |                        |                   |  | Air Conditioning / Heater              |                                |      |     |
|  |  |                      |                        |                   |  | Operation                              | <ul> <li>✓</li> </ul>          |      |     |
|  |  |                      |                        |                   |  | Electrical / Accessories               |                                |      |     |
| Seats  | marks  |                      |                        |                   |  | Head lights                            | ~                              |      |     |
| Carpets  | wear   |                      |                        |                   |  | Tail lights                            | ~                              |      |     |
|  |  |                      |                        |                   |  | Indicators                             | ~                              |      |     |
| Panels   | wear   |                      |                        |                   |  | Dashboard warning lights               | ~                              |      |     |
| Dashboa  | rd Good  |                      |                        |                   |  | Wipers (front & rear)                  | ~                              |      |     |
|  |  |                      |                        |                   |  | Window winder FL                       | ~                              |      |     |
| General Comments   |  |                      |                        |                   |  | Window winder FR                       | ~                              |      |     |
|  | <u>ioninents</u>                               |                      |                        |                   |  | Window winder RL                       | ~                              |      |     |
|  |  |                      |                        |                   |  | Window winder RR                       | ~                              |      |     |
|  |  |                      |                        |                   |  | Rear view mirrors                      | <b>v</b>                       |      |     |
|  |  |                      |                        |                   |  | Radio (basic test only)                | ~                              |      |     |
|  |  |                      |                        |                   |  | CD (basic test only)<br>Number of keys | 2                              |      | ~   |
|  |  |                      |                        |                   |  |  | 2                              |      |     |
|  |  |                      |                        |                   |  | Remote locking                         | <ul> <li></li> <li></li> </ul> |      |     |
| Engine Timing Mechanism:       Timing Chain         Sat. Nav. (basic test only)  |  |                      |                        |                   |  |  | ~                              |      |     |
| Evidence of Cam Belt Replacement: Not Applicable Kms:  |  |                      |                        |                   |  | Reversing camera                       |                                |      | ~   |
|  |  | • IN                 |                        |                   |  |  | ~                              |      |     |
| Inspected by: Melissa Wilson Date: 09 Apr 2025   |  |                      |                        |                   |  |  |                                |      |     |

I have read and understood this condition guide.

Name: .....

Signature: .....