

Report ID: 26,673,087 2 Version: 09 May 2025 Created:

Make:	Mitsubishi	Model:	ASX	Body Style:	SUV		Pass	Fail	N/A
Year:	2020	Registration:	NCQ758	Reg Expiry:	01 Jul 2025	Engine			
WoF Expiry:	22 May 2026	Odometer:	129,307 Kms	Good No:	26673087	Oil level	~		
VIN:	JMFXTGA2WMU002167	Next Service:	140000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tr	lis can be arranged to	r an additional C	.narge.	Coolant condition	~		
	S SC S		S P SC S SC			Performance	~		
Key: S = scratch		=(0)		5(0)-		Radiator / Hoses (visual)	~		
						Transmission			
R = rust	sc w			10	Ell ssc w	Operation	~		
PT = paint defe	ect NP	1				Noise	~		
C = crack				TT	SC	Clutch			~
P = pin dent	SDSC HI				24116	CV joints	~		
* = decals SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
	SC S	\sim	S P SC S SC	W	S P SC	Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
Stone chips front windscreenn						Left front	4 mm		mm
						Right front	4	.5	mm
						Left rear	3.	.5	mm
Conditions During Body Inspection: Dry						Right rear	4.5 mm		mm
					Spare	Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
No underbody inspection						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	woor					Tail lights	~		
	wear					Indicators	~		
Panels	wear					Dashboard warning lights	~		
Dashboa	rd Card					Wipers (front & rear)	~		
Dastibua	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanicm: Timing Chain						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Melissa Wilson Date: 09 May 2025									

I have read and understood this condition guide.

Name:

Signature: