

Report ID: 26,673,115 1 Version: 25 Mar 2025 Created:

Make:	Mazda	Model:	CX-5	Body Style:	SUV		Pass	Fail	N/A
Year:	2020		NFF336	Reg Expiry:	30 Apr 2025	Engine			1
WoF Expiry:		Odometer:	113,627 Kms	Good No:	26673115	Oil level	~		
VIN:	JM0KF4WLA0041768	Next Service:		Service Histor		Smoke & fumes	~		<u> </u>
			·		-	Performance	~		
	port is not a warranty	avation is maala	for one and miles as	Dauta hava nat	heen discontined or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	nical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	SC S P SC	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	scw 6/6			TIN	E S	Operation	~		
R = rust PT = paint def	ect NIP			$\left(\left \right\rangle \right)$		Noise	~		
C = crack					R P SC	Clutch	-		~
P = pin dent	HIC				세비	CV joints	~		
* = decals	PSC 916			-Jul-	ALL ALL	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
Deskulas		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread		of tyre	L 25)
Excessive stone chips on bonnet and front bumper.									mm
Minor spider rust on roof.6						Right front	5.		mm
						Left rear	5.		mm
Condition	as During Pody Inc	noction	Dest			Right rear	5.		mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-	·				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Good						Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		<u> </u>
Panels	Good					Dashboard warning lights	~		<u> </u>
	Good					Wipers (front & rear)	~		<u> </u>
Dashboa	ird Good					Window winder FL	~		<u> </u>
	I					Window winder FR	~		<u> </u>
General Comments						Window winder RL	~		+
1 remote key dose not have emergency blade. Emergency shift release switch cap is missing.						Window winder RR	~		<u> </u>
	-, sole not have emerg	,, Sidder Enfe	Servey sintercicuse sw		· J·	Rear view mirrors	~		+
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)			~
						Number of keys	3		Ĺ
Road Conditions During Test Drive: Dry						Central locking	·		
Road Conditions During Test Drive: Dry						Remote locking	~		<u> </u>
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		<u> </u>
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
	-					_			<u> </u>
Inspected by: Yuki Itohara Date: 25 Mar 2025									

I have read and understood this condition guide.

Name: