

Report ID: 26,674,319 6 Version: 05 Apr 2025 Created:

| Make: | Ford | Model: | Transit | Body Style: | Van | | Pass | Fail | N/A |
|--|-------------------------|---------------|------------------------|--|----------------------|--|--------|------|-----|
| Year: | 2018 | Registration: | PPP185 | Reg Expiry: | 10 Oct 2025 | Engine | | | L |
| WoF Expiry: | 04 Apr 2026 | Odometer: | 155,094 Kms | Good No: | 26674319 | Oil level | ~ | | |
| VIN: | WF03XXTTG3HA43347 | Next Service: | 168,977kms | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | | for ago and milaago | Darts have not | been dismonthed or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends | | | | | | Cooling System | | | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | | -0 | P SC | -01- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | L |
| D = dent R = rust | SC DE | | | 715 | HILW | Operation | ~ | | |
| PT = paint defe | | | | $\left(\left \left(\right) \right\rangle \right)$ | | Noise | ~ | | |
| C = crack | | | | | P SC | Clutch | | | ~ |
| P = pin dent | INCO HIC | | | | 74114 | CV joints | ~ | | |
| * = decals | PSC 91 | | | | ELD'S | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| w = significan | SC S | | S SC | | Р | Performance | ~ | | |
| Body Insr | pection Comments | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | Left front 5.0 mn | | | mm | |
| | | | | | | Right front | 4.0 mm | | mm |
| | | | | | | Left rear 3.0 | | .0 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 3.0 mm | | |
| | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| Shock absorbers | | | | | | | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| Carpote | A | | | | | Tail lights | ~ | | |
| Carpets | Average | | | | | Indicators | ~ | | |
| Panels | Rips in car | go area. | | | | Dashboard warning lights | ~ | | |
| Daabbaa | | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd Good | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| <u>General Comments</u> | | | | | | Window winder RL | | | ~ |
| 9 seater die | sel auto Transit minibu | S | | | | Window winder RR | | | ~ |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| CD (ba | | | | | | | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Dry Central lockin | | | | | | | ~ | | |
| Enging Ti | ning Machanisme | Timeline | Chain | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | or Cam Bert Replac | ement: N | lot Applicable | Kms: | | Reversing camera | ~ | | |
| Inspected by: Daryll Timms Date: 20 Mar 2025 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: