

# **Basic Vehicle Condition Guide**

Report ID: 26,674,388


Version:

Created: 02 Apr 2025

Make: Model: Mazda Atenza **Body Style:** Wagon Year: 2005 Registration: EKJ232 Reg Expiry: 09 May 2025 **Odometer:** WoF Expiry: 10 Sep 2025 195,030 Kms **Good No:** 26674388 VIN: 7A8C1390708126792 Next Service: 205,000 Service History: Yes

#### Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



#### **Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Headlights are faded. Stone chips in front screen.

Conditions During Body Inspection: Dry

### **Under Carriage & Under Bonnet Inspection Comments**

Tested battery and passed. Vehicle has belly pans. Runs on 91/95 octane fuel

<u>Interior Comments</u>		
Seats	Average	
Carpets	Average	
Panels	Average	
Dashboard	Average	

## **General Comments**

Air conditioning and heating are good.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Gary Adams Date: 21 Mar 2025

Name: .....

Pass	Fail	N/A		
~				
~				
~				
~				
~				
~				
~				
~				
~				
		~		
~				
~				
~				
~				
depth	of tyre	es)		
6.0		mm		
6.0		mm		
2.0		mm		
7.0		mm		
	N/A			
•				
~				
~				
~				
Air Conditioning / Heater				
Operation 🗸				
~				
~				
~				
>				
~				
~				
~				
~				
<b>'</b>				
~				
~				
~				
1				
~				
~				
		~		
	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ			

Signature: .....