

Basic Vehicle Condition Guide

Report ID: 26,675,294


Version: 4

Created: 12 Apr 2025

Make: Model: Mitsubishi **Eclipse Cross Body Style:** SUV Year: 2024 Registration: **RBR673** Reg Expiry: 04 Oct 2025 **Odometer:** WoF Expiry: **Good No:** 11 Apr 2027 9,138 Kms 26675294 **Next Service:** VIN: JMFXTGK1WPZ007102 24,000 Kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Under Carriage & Under Bonnet Inspection Comments

Conditions During Body Inspection:

| <u>Interior Comments</u> | | | | |
|--------------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Average | | | |

Dry

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Greg Morgan Date: 25 Mar 2025

| | Pass | Fail | N/A | |
|------------------------------------|------------------|---------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | V V | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | \(\sigma \) | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | 1 | ı | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | |
| Left front | 6 | .0 | mm | |
| Right front | 6 | .0 | mm | |
| Left rear | 7 | .0 | mm | |
| Right rear | 7.0 | | mm | |
| Spare | | Yes | | |
| Suspension | ı | ı | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | • | | | |
| Tail lights | • | | | |
| Indicators | • | | | |
| Dashboard warning lights | • | | | |
| Wipers (front & rear) | | | | |
| Window winder FL | V V V V | | - | |
| Window winder FR | | | | |
| Window winder RL | V V | | | |
| Window winder RR Rear view mirrors | | | | |
| Radio (basic test only) | <i>V</i> | | - | |
| CD (basic test only) | | | ., | |
| Number of keys | 2 | | | |
| Central locking | • | | | |
| Remote locking | ., | | _ | |
| Sat. Nav. (basic test only) | | | ., | |
| Reversing camera | | | | |
| eversing cumera | | | | |

I have read and understood this condition guide.

Name:

Signature: