

Report ID: 26,676,235 1 Version: 03 Apr 2025 Created:

Make:	Ssangyong	Model:	Korando	Body Style:	SUV		Pass	Fail	N/A
Year:	2012	<b>Registration:</b>	RAS572	<b>Reg Expiry:</b>	19 Sep 2025	Engine	•		
WoF Expiry:	14 Apr 2026	Odometer:	147,402 Kms	Good No:	26676235	Oil level	~		
VIN:	KPTB0A18SCP077909	Next Service:	152,000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	Coolant condition	~						
						Performance	~		
Key:	D	-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = ruct SC D D D D D D D D D D D D D D D D D D						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack				$+ \vee$		Clutch	~		
P = pin dent	HIC				거네	CV joints	~		
* = decals	s 916			- NL		Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs						Performance	~		
		Note: son	ne defects & blemishe	s may not be disc	blaved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed tread	•	oftvre	) (24
						Left front	· ·	4.0 mm	
						Right front	6		 mm
						Left rear		.0	mm
Conditions During Pody Inspections						Right rear			mm
Conditions During Body Inspection: Dry						Right rear     6.0     mm       Spare     Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance	~		
Tested batt	ery and passed.					Steering performance			
						Shock absorbers	レ レ		
							V		
						Air Conditioning / Heater			
Interior Comments						Operation   Electrical / Accessories			
Seats	Average						~		
Carpets	Average					Tail lights Indicators	~		
							~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General Comments						Window winder FR	~		
						Window winder RL	~		
Air conditioning and heating systems good temperature at inspection time						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
						Sat. Nav. (basic test only)			~
	ог сапт вен керіас	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Gary Adams						Date: 24 Mar 20	25		

I have read and understood this condition guide.

Name: .....

Signature: .....