

Basic Vehicle Condition Guide

Report ID: 26,677,709


Version:

05 May 2025 Created:

Make: Model: Holden Captiva 7 **Body Style:** SUV Year: 2014 Registration: HGP94 Reg Expiry: 19 Aug 2025 WoF Expiry: **Odometer:** 20 Jan 2026 112,544 Kms **Good No:** 26677709 VIN: KL3CD265JDB094858 Next Service: 125000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Minor stone chips on windscreen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

All wheel drive

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

| | _ |
|---------|----------|
| General | Comments |

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

> 24 Mar 2025 Date:

| | Pass | Fail | N/A | |
|------------------------------|-----------------|---------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | <i>v v</i> | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | • | • | • | |
| Coolant condition | ~ | | | |
| Performance | ~ | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | • | ! | • | |
| Operation | ~ | | | |
| Noise | V | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | d depth | of tyre | es) | |
| Left front | 7 | .0 | mm | |
| Right front | 7.0 | | mm | |
| Left rear | 4.0 | | mm | |
| Right rear | 3.5 | | mm | |
| Spare | Yes | | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | \(\triangle \) | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation 🗸 | | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | \(\times \) | | | |
| Window winder FL | ~ | | | |
| Window winder FR | v v | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | ~ | | | |
| Radio (basic test only) | ~ | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | | | |
| Central locking | · | | | |
| Remote locking | V | | | |
| Sat. Nav. (basic test only) | ~ | | | |
| | ., | | | |
| Reversing camera | | | | |

I have read and understood this condition guide.

Jaykib Collins

Name:

Signature: