

Basic Vehicle Condition Guide

Report ID: 26,680,945


Version:

01 Apr 2025 Created:

Make: Model: Nissan Elgrand **Body Style:** Wagon Year: 2010 Registration: NSH254 Reg Expiry: 23 Mar 2025 **Odometer:** WoF Expiry: 25 Mar 2026 195,639 Kms **Good No:** 26680945 **Next Service:** VIN: 7AT0DH6MX21001202 205400 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Right Rear Door - Automatic Open Not Working

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|---------|--|--|--|
| Seats | Good | | | |
| Carpets | Good | | | |
| Panels | Average | | | |
| Dashboard | Good | | | |

General Comments

Oil Seepage - Expected for Age & Mileage

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

01 Apr 2025 Beatrice Nelson Inspected by: Date:

Name:

| | Pass | Fail | N/A |
|------------------------------|--------------|---------|-----|
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | <i>V V</i> | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | 4.5 | | mm |
| Right front | 4.5 | | mm |
| Left rear | 5.5 | | mm |
| Right rear | 6.0 | | mm |
| Spare | No | | |
| Suspension | 1 | | |
| Suspension performance | ~ | | |
| Steering performance | V V | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | 1 | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | \(\times \) | | |
| Window winder FL | ~ | | |
| Window winder FR | \(\times \) | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | v | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | L | |
| Central locking | · | | |
| Remote locking | ~ | | |
| Sat. Nav. (basic test only) | <u> </u> | | V |
| Reversing camera | ~ | | - |
| g camera | | | |

Signature: