

Report ID: 26,681,277 4 Version: 03 Apr 2025 Created:

Make:	BMW	Model:	1161	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2011	Registration:	MAK645	Reg Expiry:	04 Mar 2026	Engine	1	1	1
WoF Expiry:	01 Feb 2026	Odometer:	160,670 Kms	Good No:	26681277	Oil level	~		
VIN:	WBA1A12070E946214	Next Service:	168000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	V		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	SC	-0		-161-	D	Radiator / Hoses (visual)	v		
S = scratch						Transmission			
D = dent	ssc 6/6			The	S SC	Operation	~		
R = rust				r In	THIA	Noise	~		
PT = paint defect C = crack						Clutch	•		~
P = pin dent	Ho					CV joints			~
* = decals	SPSC PK			AL.		Wheel bearings	~		
SC = stone chips						Brakes	V		
W = significant scuffs R SC SC SC						Performance			1
		Note: con			laved in the diagram	Hand Brake			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							danth	ofture	
No spare wheel provided by manufacturer but emergency tire inflation device is in the boot						Left front	owest observed tread depth of tyres)		
									mm
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Dry						Right rear			mm
Under Carriage & Under Bonnet Inspection Comments						Spare N/A			
onder carnage & onder bonnet inspection comments					Suspension			1	
Tested batt	ery and passed. Runs or	n 95 octane fuel.	Vehicle has belly pans			Suspension performance	~		
						Steering performance	~		-
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats	Average a	ge of vehicle				Head lights	~		
Carpets	Average					Tail lights	~		
Carpets	Avelage					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd A					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
- ·	_					Window winder FR	~		
<u>General Comments</u>					Window winder RL	~			
Air conditioning and heating systems ok at inspection time.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		1
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
L								1	
Inspected by: Gary Adams Date: 2							25		
I have read and understood this condition guide. Name:									