

Basic Vehicle Condition Guide

Report ID: 26,684,260


Version:

Created: 01 Apr 2025

Make: Model: Honda CRV **Body Style:** Wagon Year: 2005 Registration: **GUH743** Reg Expiry: 14 Apr 2025 **Odometer:** WoF Expiry: 05 Apr 2025 226,620 Kms **Good No:** 26684260 VIN: 7AT08G7HX13004871 **Next Service: Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Spare wheel bold and flat/rear bumper misaligned/fender mirror glass missing

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

All wheel drive/major engine oil leak/

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	scratch marks		
Dashboard	Average		

General Comments

Rear differential binding/belt noise on heavy acceleration/

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Uriah Pepene Date: 26 Mar 2025

Name:

Pass V V V V V	Fail	N/A
V V V V V V		
\(\times \) \(\t		
\(\times \)		
<i>V V V V</i>		
<i>V V V</i>		
<i>V V V</i>		
V V		
<i>V</i>		
<i>v</i>		1
v		
		-
~		
'		
'		
depth	of tyre	es)
3.	.0	mm
3.	.0	mm
6.0		mm
6.0 m		mm
	Yes	
	~	
~		
~		
~		
~		
~		
~		
v		
·		
		
		_
		_
		'
V		1
	3 3 3 6 6 6 V V V V V V V V V V V V V V	6.0 Yes V V V V V V V V V V V V V

Signature: