

Report ID: 26,688,432 4 Version: 23 Jun 2025 Created:

Make:	Volkswagen	Model:	Polo	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2014	Registration:	HKQ941	Reg Expiry:	01 Oct 2025	Engine				
WoF Expiry:	23 Apr 2026	Odometer:	101,512 Kms	Good No:	26688432	Oil level	~			
VIN:	WVWZZZ6RZEY222539	Next Service:	111,000km	Service Histor	y: Yes	Smoke & fumes	~			
						Performance	~			
	port is not a warranty		for ago and milaago	Parts have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	charge.	Coolant condition	~			
						Performance	~			
Key:	SC	-0	SD S			Radiator / Hoses (visual)	~			
S = scratch						Transmission				
							Operation 🖌			
R = rust PT = paint def				r In	JHIH	Noise	~			
C = crack				+	SC	Clutch	•		~	
P = pin dent	Htc					CV joints	~		•	
* = decals	- Mik			AL.	ELTR-S	Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs SC W DW D W						Performance	~			
		Note con	he defects & blemishes		laved in the diagram	Hand Brake	~			
Body Insp	pection Comments		le delects & blemisnes	inay not be disp	hayed in the diagram		•	- f t wa		
Windscreen stone chips						Tyres (lowest observed tread depth of tyres)				
						Left front	4.		mm	
						Right front	5.		mm	
						Left rear	5.		mm	
Conditions During Body Inspection: Dry						Right rear				
Under Carriage & Under Bonnet Inspection Comments						Spare Yes				
	inage & Under Bui	metinspectic	<u>In comments</u>			Suspension				
						Suspension performance	~			
Front whee	l drive					Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Commonts						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpote	Card					Tail lights	~			
Carpets	Good					Indicators	~			
Panels	Good					Dashboard warning lights	2			
Deckle						Wipers (front & rear)	<			
Dashboa	rd Good					Window winder FL	~			
						Window winder FR	~			
General Comments						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2		•	
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
<u> </u>										
Inspected by: Rowan Fey Date: 10 Apr 2025										

I have read and understood this condition guide.

Name:

Signature: