

Report ID: 26,689,460 1 Version: 07 Apr 2025 Created:

Make:	MG	Model:	HS	Body Style:	SUV		Pass	Fail	N/A
Year:	2023	<b>Registration:</b>	QGZ648	<b>Reg Expiry:</b>	05 Mar 2025	Engine			
WoF Expiry:		Odometer:	43,323 Kms	Good No:	26689460	Oil level	~		
VIN:	LSJA24393PN052928	Next Service:	45000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage.	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
	P SC		D SC S P SC		SC	Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	SC D			210	S SC	Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack						Clutch			~
P = pin dent	sc de				74114	CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significant	W		D P SC P SC			Performance	~		
   Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	d depth	of tyre	es)
Stone chip front windscreenn						Left front 7			mm
						Right front	6.	.5	mm
						Left rear	6	5	mm
Conditions During Body Inspection: Dry						Right rear	6.5 mm		
						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Noundarbo	ody inspection					Suspension performance	~		
	buy inspection					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			L
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	eats Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
PHEV						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Con	Central locking	~							
			Dry			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
	11 Molioco 14/1						)F		
Inspected by: Melissa Wilson Date: 07 Apr 2025									

I have read and understood this condition guide.

Name: .....

Signature: .....