

Report ID: 26,690,860 3 Version: 17 Jun 2025 Created:

| Make: | Subaru | Model: | Impreza | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|---|----------------------|------------------------|--------------------|----------------------|--|--------|------|-----|
| Year: | 2014 | Registration: | MMU933 | Reg Expiry: | 18 Nov 2025 | Engine | • | | • |
| WoF Expiry: | 18 Jan 2026 | Odometer: | 125,934 Kms | Good No: | 26690860 | Oil level | ~ | | |
| VIN: | 7AT0GF09X19073477 | Next Service: | 135,936kms | Service Histor | y: No | Smoke & fumes | ~ | | |
| No. The | | | | | | Performance | ~ | | |
| | port is not a warranty a quide only. Conside | | for age and mileage | . Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and tr | lis can be arranged ic | or an additional C | narge. | Coolant condition | ~ | | |
| | S SC | | SC W SC | | S SC | Performance | ~ | | |
| Key: S = scratch | | =(0) | | 5(0)- | | Radiator / Hoses (visual) | ~ | | |
| D = dent | 1 E | | | | AD FROM | Transmission | • | | • |
| R = rust | scw | | | 10 | S SC W | Operation | ~ | | |
| PT = paint defe | ect NP | | | | | Noise | ~ | | |
| C = crack | | | | TTX. | SC | Clutch | | | ~ |
| P = pin dent | sc de | | | | 74IIL | CV joints | ~ | | |
| * = decals | | 10 | | 10 | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| in significant | SC | C | P SC S | | SC | Performance | ~ | | |
| Body Inst | pection Comments | Note: som | ne defects & blemishes | s may not be disp | layed in the diagram | Hand Brake | ~ | | |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | ès) |
| Chips left A pillar | | | | | | Left front | 3 | .0 | mm |
| | | | | | | Right front | 2 | .5 | mm |
| | | | | | | Left rear | 2 | .0 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 3.0 mm | | |
| | | | | | | Spare N/A | | | |
| Under Ca | rriage & Under Bor | nnet Inspectio | on Comments | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | _ | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| Carpets | Cood | | | | | Tail lights | ~ | | |
| | Good | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| Dashboa | rd c i | | | | | Wipers (front & rear) | ~ | | |
| | rd Good | | | | | Window winder FL | ~ | | |
| | . | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | | | ~ |
| | | | | | | Number of keys | 2 | I | |
| Road Con | ditions During Tes | t Drive: | Dry | | | Central locking | ~ | | |
| | ning Mashering | T '' | | | | Remote locking | ~ | | |
| - | ming Mechanism: | Timing (| | I. | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| Inspected | d by: Dean Sinclair | | | | | Date: 26 Mar 20 | 25 | | |
| | a by. Dean Sincian | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: