

I have read and understood this condition guide.

Report ID: 26,691,575 6 Version: 28 Apr 2025 Created:

Signature:

Make:	Skoda	Model:	Scala	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2020	Registration:	MRU940	Reg Expiry:	11 Oct 2025	Engine			
WoF Expiry:	23 Jan 2026	Odometer:	86,898 Kms	Good No:	26691575	Oil level	~		
VIN:	TMBFK7NW5L3055542	Next Service:	96332	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Consid		for age and mileage.	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a run mechan	ical inspection prior to	purchase and tr	lis can be arranged to	or an additional C	narge.	Coolant condition	~		
			SPW SPW		SW	Performance	~		
Key: S = scratch		=(0)		5(0)-		Radiator / Hoses (visual)	~		
						Transmission			
R = rust	S SC W			10	EII/SW	Operation	~		
PT = paint def	ect NP	1				Noise	~		
C = crack						Clutch			~
P = pin dent	ssc die				74Hb	CV joints	~		
* = decals		1 O		10		Wheel bearings	<		
SC = stone chips W = significant scuffs						Brakes			
	S W		S P W S W	SW	S W	Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
					Tyres (lowest observed tread depth of tyres)				
						Left front	7.	.0	mm
						Right front	7.	.0	mm
						Left rear	5.	.0	mm
Conditions During Body Inspection: Dry						Right rear	5.0 mm		
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	9000					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dashboa	9000					Window winder FL	~		
Concret	ommonte					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
Front whee	l drive					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry							~		
Engine Ti	ming Mechanism:	Timing (Remote locking	~		
-	-			Kmc		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: My Auto Shop Date: 31 Mar 2025									

Name: