

Basic Vehicle Condition Guide

Report ID: 26,696,751


Version: 2

Created: 16 Jun 2025

Make: BMW Model: 218D **Body Style:** Hatchback Year: 2018 Registration: RBR698 Reg Expiry: 15 Dec 2025 WoF Expiry: **Odometer:** 09 May 2026 93,151 Kms **Good No:** 26696751 VIN: WBA2C120007A38399 Next Service: 103,145 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Dry

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Unknown

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Tyler Le Bherz Date: 21 May 2025

Name:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	\(\times \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission	•			
Operation	~			
Noise	~			
Clutch			~	
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front	7	.0	mm	
Right front	7.0		mm	
Left rear	7.0		mm	
Right rear	7.0		mm	
Spare		N/A		
Suspension		1		
Suspension performance	~			
Steering performance	\(\sigma \)			
Shock absorbers	~			
Air Conditioning / Heater	1	I		
Operation	~			
Electrical / Accessories	1	I	1	
Head lights	<i>'</i>			
Tail lights	•			
Indicators	•			
Dashboard warning lights	\(\times \)			
Wipers (front & rear)	•			
Window winder FL Window winder FR	VVV			
Window winder RL	-			
Window winder RR				
Rear view mirrors	V			
Radio (basic test only) CD (basic test only)	'		.,	
Number of keys	2			
Central locking	•			
Remote locking	<i>y</i>			
Sat. Nav. (basic test only)			1	
Reversing camera	~			
eversing curriera				

Signature: