

Report ID: 26,696,779 2 Version: 21 May 2025 Created:

Make:	Toyota	Model:	Aqua	Body Style: Hatchback	1		Pass	Fail	N/A	
Year:	2014	Registration:	, iquu	Reg Expiry:	End	Engine				
	02 May 2026	Odometer:	71,216 Kms	Good No: 26696779		)il level	~			
VIN:	7AT0H65YX25305943			Service History: No		moke & fumes	~			
	78101051825505945	HEAT DEI VICE.	01,213 KIII3		┙┝──	erformance	-			
	port is not a warranty						~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Noise				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
					५ ⊢	oolant condition	~			
Key:				SC		erformance	~			
S = scratch						Radiator / Hoses (visual)				
D = dent						Transmission				
R = rust						peration	~			
PT = paint defect						loise	~			
C = crack P = pin dent						lutch			~	
*= decals						V joints	~			
SC = stone chips						Wheel bearings				
W = significant scuffs						Brakes				
						erformance	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						land Brake	~			
					I	Tyres (lowest observed tread depth of tyres)				
						eft front	6.5	5	mm	
						ight front	7.0	)	mm	
						eft rear	7.0	)	mm	
Conditions During Body Inspection: Dry						ight rear	7.0 mm		mm	
						Spare N/A				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						uspension performance	~			
						teering performance	~			
						hock absorbers	~			
						Conditioning / Heater				
						Operation 🖌				
Interior Comments					Ele	ectrical / Accessories				
Seats	Good				н	lead lights	~			
Carpets	Good					ail lights	~			
	Good				In	ndicators	~			
Panels	Good				D	ashboard warning lights	~			
Dashboa	rd c i				W	Vipers (front & rear)	~			
	rd Good				N	Vindow winder FL	~			
					<u> </u>	Vindow winder FR	~			
<u>General Comments</u>					W	Vindow winder RL	~			
One key blade missing						Vindow winder RR	~			
					R	ear view mirrors	~			
						adio (basic test only)	~			
						D (basic test only)	~			
						lumber of keys	1			
Road Conditions During Test Drive: Dry						entral locking	~			
						emote locking	~			
						at. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						eversing camera	~			
Inspected by: Dean Sinclair Date: 07 May 2025										

I have read and understood this condition guide.

Name: .....

Signature: .....