

Report ID: 26,696,831 3 Version: 16 May 2025 Created:

| Make: | Toyota | Model: | Corolla | Body Style: | Wagon | | Pass | Fail | N/A |
|--|---|----------------------|------------------------|-------------------|-----------------------|--|------------|------|----------|
| Year: | 2017 | Registration: | | Reg Expiry: | | Engine | | | |
| WoF Expiry: | 02 May 2026 | Odometer: | 77,244 Kms | Good No: | 26696831 | Oil level | ~ | | |
| VIN: | 7AT0H607X25149685 | Next Service: | 87,238 Kms | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty a quide only. Conside | eration is made | for age and mileage | . Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a run mechan | lical inspection phor to | purchase and t | his can be allanged ic | | Lindige. | Coolant condition | ~ | | |
| | S | | | | | Performance | ~ | | |
| Key: S = scratch | | =(0) | | 5(0)- | | Radiator / Hoses (visual) | ~ | | |
| D = dent | | | | | | Transmission | | | |
| R = rust | | | | 10 | | Operation | ~ | | |
| PT = paint defe | ect NP | | | | | Noise | ~ | | |
| C = crack | | | | | | Clutch | | | ~ |
| P = pin dent | sc de | | | | 241 <u>16</u> | CV joints | ~ | | |
| * = decals | | 10 | | 70 | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| | | | | | | Performance | ~ | | |
| Body Insp | pection Comments | Note: son | ne defects & blemishes | s may not be disp | played in the diagram | Hand Brake | ~ | | |
| | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 5. | .0 | mm |
| | | | | | | Right front | 5. | .0 | mm |
| | | | | | | Left rear | 5. | .0 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | ear 5.0 mr | | |
| | | | | | | Spare N/A | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| Carpets | Cood | | | | | Tail lights | ~ | | |
| | Good | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| Dashboa | rd Good | | | | | Wipers (front & rear) | ~ | | <u> </u> |
| | rd Good | | | | | Window winder FL | ~ | | |
| Concert | | | | | | Window winder FR | ~ | | <u> </u> |
| | <u>Comments</u> | | | | | Window winder RL | ~ | | <u> </u> |
| . | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | <u> </u> |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| Engine Timing Mechanicmy Timing Chain | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| Inspected by: Caleb Spicer Lee Date: 08 May 2025 | | | | | | | | | |
| | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: