

Report ID: 26,697,034 1 Version: 12 May 2025 Created:

Make:	Toyota	Model:	Aqua	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2014	<b>Registration:</b>		Reg Expiry:		Engine				
WoF Expiry:	07 May 2026	Odometer:	88,002 Kms	Good No:	26697034	Oil level	~			
VIN:	7AT0H65YX25294066	Next Service:	100000	Service Histor	r <b>y:</b> No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty a quide only. Conside		for age and mileage	. Parts have not	been dismantled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	lical inspection prior to	purchase and t	his can be arranged fo	or an additional	charge.	Coolant condition	~			
	D		S			Performance	~			
Key:				5(0)-		Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission	Transmission			
D = dent R = rust	s bla	1		710	HIV	Operation	~			
PT = paint defe	ect NP	IT I		$\left[ \left( \right) \right]$		Noise	~			
C = crack						Clutch			~	
P = pin dent	P				7414	CV joints	~			
* = decals		10		To .		Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
vv = significan	P				D	Performance	~			
Body Incr	position Commonts	Note: sor	ne defects & blemishe	s may not be disp	played in the diagram	Hand Brake	~			
Body Inspection Comments						<b>Tyres</b> (lowest observed tread depth of tyres)			1 2S)	
· ·						Left front	6	.0	mm	
						Right front	6	.0	mm	
						Left rear	5	.0	mm	
Conditions During Body Inspection: Wet						Right rear			mm	
Conditions During Body inspection. Wet						Spare No				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater			<u> </u>	
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
						Tail lights	~		-	
Carpets	Good					Indicators	~			
Panels	Good					Dashboard warning lights	~		<u> </u>	
						Wipers (front & rear)	~		1	
Dashboa	ord Good					Window winder FL	~		1	
	I					Window winder FR	~		1	
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~		1	
						Rear view mirrors	~		1	
						Radio (basic test only)	~		1	
						CD (basic test only)			~	
						Number of keys	2	1		
Road Conditions During Test Drive: Wet						Central locking	~			
						Remote locking	~		1	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	Not Applicable	Kms:		Reversing camera	~		+	
								1		
Inspected by: Chris Buckley Date: 09 May 2025										

I have read and understood this condition guide.

Name: .....

Signature: .....